Product Change Notification

General Information			
PCN No.	E20261021-01	**Issue Date**	October 21, 2026
Product Model	PH920-M280		
Level of Change	☐ Critical: Immediate change required ■ Advised: Implementation strongly recommended ☐ Recommended: Optional, but suggested ☐ Informational: No immediate action required		

Change Details	
Title of Change	Firmware Version Update for Apacer Industrial PH920-M280 SSD
Type of Change	■ Firmware ☐ Hardware ☐ BOM Change ☐ Packaging ☐ Production Process ☐ Technical Document ☐ Others
Description of Change	1. Fixed firmware index errors after Sudden Power-Off Recovery (SPOR). 2. Enhanced the garbage collection (GC) process to prevent free-block depletion after SPOR. 3. Fixed incorrect negative temperature values reported in S.M.A.R.T.
Reason for Change	Firmware update to improve system stability

Part Numbers Affected
Please refer to the Appendix below for the list of pre- and post-change part numbers.

Key Milestones	
Sample Availability Date	October 30, 2026
Implementation Date	October 30, 2026

Customer Acknowledgement
Should you have any questions or concerns regarding this notification, please contact your Apacer sales representative. If no response is received within 30 days from the date of this notification, it will be considered as acceptance of the change, and the change will be implemented according to the key milestones outlined above.

Issuing Authority	
Authorized By	Jessica Yin
Job Title	Director of Product Center

Apacer Technology Inc.
Add: 1F, No.32, Zhongcheng Rd., Tucheng District, New Taipei City, Taiwan, R.O.C.
Tel: +886-2-2267-8000
https://www.apacer.com/en

[Appendix: Part Numbers Affected]

Current PN			New PN		
Capacity	Standard Temp	Wide Temp	Capacity	Standard Temp	Wide Temp
160GB	B92.929KYV.00216	B92.929KZV.00316	160GB	B92.929KYV.00220	B92.929KZV.00320
320GB	B92.929LYU.00216	B92.929LZU.00216	320GB	B92.929LYU.00220	B92.929LZU.00220
640GB	B92.929MYU.00216	B92.929MZU.00216	640GB	B92.929MYU.00220	B92.929MZU.00220