Product Change Notification (PCN) Announcement

Title	InnoAgent OOB module firmware change notification	Date	2026/Feb/09	Ref No.	E260002
Models	EZ2N-0XL1				
Level	◉ Critical ○ Major ○ Minor ○ Notice				

Description

This PCN is being issued to address that Innodisk InnoAgent OOB module is going to upgrade product firmware (F/W).

Current FW: iCAP_SDK_img_v1.1.1_lib_v1.1.0_app_v1.1.3

New FW: iCAP_SDK_img_v1.2.0_lib_v1.1.0_app_v1.2.1

Affected Component Table

Model	Current Part Number	New Part Number
EZ2N-0XL1	EZ2N-0XL1-W1%	N/A
EZ2N-0XL1	EZ2N-0XL1-W3%	N/A
EZ2N-0XL1	EZ2N-0XL1-W4%	N/A

Desc. Note

Innodisk anticipates no negative impact to customer's application.
There is no functional implication to customer's application but improve reliability, and qualification of these changes may not be necessary.

Summary of Change

img_v1.2.0_lib_v1.1.0_app_v1.2.1
- support auto return GPIO status
- Support NUC980_UART7_PB (enable/disable via SUPPORT_OSR)
- (FEATURE) Support OS recovery function with InnoOSR through NUC980_UART7_PB
- Adjusted the initialization process to resolve the issue caused by "MQTTAgent connection failure"

Note

No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones. Innodisk apologizes for any inconvenience caused by this and appreciate your understanding.
Innodisk promises that new items deliver quality and reliability for your application. If you have any further inquiry of our products or if you have any question about the specification of it, please contact Innodisk sales person.
Thank you for your confidence in Innodisk in the past and looking forward to serving you in the near future.

Key Milestone Dates

Effective Date	2026/Mar/02

<u>*Recommend action:</u>
○ Call back ○ All stock rework ○ Running change ◉ Cut in Effective date

Customer Impact of Change and Recommended Action

Please review the content and provide specific recommendation based on this document.
Innodisk anticipates no negative impact to customer's application.There is no functional implication to customer's application but improve reliability, and qualification of these changes may not be necessary.

Revision History

Date of Revision:	Revision Number:	Remark:
2026/Feb/09	E260002	

Senior Director, JOHNNY WU
Intelligent Peripheral Appliance Div.

Assistant Manager, TONY LIU
PM Section I