



Issued date: 1 February, 2021

Product EOL Notice

Affected Model:

APC-3584A, APC-3784A, APC-3984A

APC-3585A, APC-3785A, APC-3985A

APC-3584B, APC-3784B, APC-3984B

APC-3585B, APC-3785B, APC-3985B

Last buy date: 2021/7/30

Orders are non-cancelable and non-returnable after: 2021/7/30

Last shipment date: 2021/08/31

Technical Support service Ends: 2023/8/31

Description of notice to the customer:

Aplex will be discontinuing the APC-3X84A/B and APC-3X85A/B Products. The reason of changing is due to natural decline in demand for these products.

Customer impact of change and recommended action:

Aplex will discontinue these products line, and we suggest you order ViTAM-6XX, ViTAM-8XX and ViTAM-9xx series for replacement.

We apologize for any inconvenience this may cause and we will make every attempt to support your needs. Please contact with your sales representative at sales@aplex.com for any assistance you may need.

Sincerely Yours

Lily Chiu

Project Manager of Product Management Division

Aplex Technology Inc.

APLEX Technology Inc.

15F-1, No.186, Jian Yi Road, Zhonghe District, New Taipei City 235, Taiwan

Tel:886-2-82262881

Fax:886-2-82262883