



BCM

Product Change Notice

PCN Type: HW/SYS/Kit BIOS/LAN/FW Package/Label Driver/OS Acc. Others Page: 1 of 1

PCN Number: P213701		Revision: A		Date of Publication: 09/14/2021
PRODUCT NAME	PRODUCT PART#	OLD — REV. — NEW		REVISION TYPE
RX370Q	71601-IA	1.2	1.2	Hardware

REASON OF CHANGE:
uPI Semiconductor Corp. UP7536 power multiplexer for USB switch is in shortage.

DESCRIPTION OF CHANGE:
Add uPI Semiconductor Corp. UP7550 power multiplexer for USB switch to use.

IMPACT OF CHANGE AND RECOMMEND ACTION:
This change has been thoroughly evaluated to ensure that there are no quality, reliability or functional implications to our customer.
BCM is not recommending our customer to perform additional qualification of these changes.

AFFECTED BY THIS CHANGE	
Specification	NO
Packaging	NO
Labeling	NO
BIOS	NO
Driver	NO
Hardware	YES

CUT IN DATE:
Date: November, 2021
OR
Lot#:

*Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order	X		
In Process	X		
Finished Goods		X	
RMA		X	

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on 09/13/2021.
This PCN had been **APPROVED** by BCM Procurement Department on September, 2021.

APPROVED BY

VP OF SALES	<APPROVED>	09/14/2021
--------------------	------------	------------

Signature

Date