



BCM

Product Change Notice

PCN Type: HW/SYS/Kit BIOS/LAN/FW Package/Label Driver/OS Acc. Others Page: 1 of 1

PCN Number: P224802		Revision: A		Date of Publication: 12/02/2022
PRODUCT NAME	PRODUCT PART#	OLD — REV. — NEW		REVISION TYPE
ECM-3455J	71811-IA	1.0	1.0A	Hardware
OFT10W-3455J-AN	69372	1.0	1.1	
OFT10W-3455J-WN	69373	1.0	1.1	
OFT10W-3455J-LX	69348	1.0	1.1	

REASON OF CHANGE:
 Improve boot up optimization.

DESCRIPTION OF CHANGE:
 Add 0Ω resistor on location R819.

IMPACT OF CHANGE AND RECOMMEND ACTION:
 This change has been thoroughly evaluated to ensure that there are no quality, driver and reliability implications to our customer.
 BCM is not recommending our customer to perform additional qualification of these changes.

AFFECTED BY THIS CHANGE	
Specification	NO
Packaging	NO
Labeling	NO
BIOS	NO
Driver	NO
Hardware	YES

CUT IN DATE:
 Date: December 9, 2022
 OR
 Lot#:
 *Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order	X		
In Process	X		
Finished Goods	X		
RMA		X	

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on November, 2022.
 This PCN had been **APPROVED** by BCM Procurement Department on December, 2022.

APPROVED BY

VP OF SALES	<APPROVED>	12/02/2022
--------------------	------------	------------

Signature

Date