



BCM

Product Change Notice

PCN Type: HW/SYS/Kit BIOS/LAN/FW Package/Label Driver/OS Acc. Others Page: 1 of 1

PCN Number: P233201		Revision: A		Date of Publication: 08/09/2023
PRODUCT NAME	PRODUCT PART#	OLD — REV. — NEW		REVISION TYPE
RX680R	71882-IA	1.10	1.11	BIOS

REASON OF CHANGE:

Fix USB C not functional properly.

DESCRIPTION OF CHANGE:

File name: 71882111.rom
 Message: RX680R (71882) BIOS V1.11
 Version: 1.11
 Checksum: BC98 hex
 Programming method: Using AfuEfix64.efi under UEFI.

IMPACT OF CHANGE AND RECOMMEND ACTION:

This change has been thoroughly evaluated to ensure that there are no quality, functional and compliance implications to our customer.

BCM is not recommending customer to perform additional qualification of this change.

AFFECTED BY THIS CHANGE	
Specification	NO
Packaging	NO
Labeling	NO
BIOS	YES
Driver	NO
Hardware	NO

CUT IN DATE:

Date: 08/14/2023
 OR
 Lot#:

*Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order	X		
In Process	X		
Finished Goods	X		
RMA	X		

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on 08/09/2023.
 This PCN had been **APPROVED** by BCM Procurement Department on 08/09/2023.

APPROVED BY

VP OF SALES	<APPROVED>	08/09/2023
--------------------	------------	------------

Signature

Date