

Product Change Notice

Update Firmware Version for UH110-UFD5 BiCS5 Products

Release date: Aug. 16, 2024

Dear Valued Customers,

Thank you for your business and continued support for Apacer products. This PCN is being issued to inform you of a firmware update for UH110-UFD5 BiCS5 products. Details of the change are provided in the table below. Apacer will provide all necessary support to ensure a seamless transition. If you have any questions or concerns regarding the content of this notification, please get in touch with Apacer sales representatives.

PCN Number	E240816-2	Release Date	Aug. 16, 2024
Action Levels	<div><input type="checkbox"/> Critical: Immediate change required</div> <div><input type="checkbox"/> Warning: Change as soon as possible</div> <div><input checked="" type="checkbox"/> Recommended: Optional, but suggested</div> <div><input type="checkbox"/> Informational: No immediate action required</div>		
Affected Product Model	UH110-UFD5 BiCS5		
Subject of Change			
Update firmware version to UFPA4AEA for UH110-UFD5 BiCS5 products			
Description of Change			
<p>Apacer has updated the firmware version from UFPA4ACA to UFPA4AEA, respectively, with the following changes:</p> <div><div>1. Add Secure Firmware.</div><div>2. Optimized error handling flow when host accesses non-existent LBA.</div><div>3. Fine-tune read-retry table</div></div>			
Recommended Action			
Apacer will continue to supply UH110-UFD5 BiCS5 with the old firmware, but we recommend qualifying with the latest version for improved compatibility and support.			
Affected Part Numbers			

Capacity	Existing Part Numbers		New Part Numbers	
	Standard Temperature	Wide Temperature	Standard Temperature	Wide Temperature
32GB	AN2.118HLS.00121	AN2.118HMS.00121	AN2.118HLS.00133	AN2.118HMS.00133
64GB	AN2.118JLS.00121	AN2.118JMS.00121	AN2.118JLS.00133	AN2.118JMS.00133

Schedule

Sample available date: Aug. 16, 2024

Product Center
Apacer Technology Inc.