

Product Change Notification

Issue Date: September 29, 2024

Product Name: SBC series

Status: Running change

This notice is to inform you of changes to the: WAFER-TGL-U / KINO-TGL-U / KINO-EHL / WAFER-EHL / HYPER-EHL / KINO-ADL-P / WAFER-ADL-P / WAFER-ADL-N series.

Reason for Change

1. Intel® Ethernet Controller I225 shortage issues.

Description of Change

1. Change LAN IC from Intel® Ethernet Controller I225-LM / I225-V to Intel® Ethernet Controller I226-LM / I226-V.

Affected Model

Affected Model	New Version
WAFER-TGL-U-CE-R11	WAFER-TGL-U-CE-R12
WAFER-TGL-U-i3-R11	WAFER-TGL-U-i3-R12
WAFER-TGL-U-i5-R11	WAFER-TGL-U-i5-R12
WAFER-TGL-U-i7-R11	WAFER-TGL-U-i7-R12
KINO-TGL-U-CE-R10	KINO-TGL-U-CE-R11
KINO-TGL-U-i3-R10	KINO-TGL-U-i3-R11
KINO-TGL-U-i5-R10	KINO-TGL-U-i5-R11
KINO-TGL-U-i7-R10	KINO-TGL-U-i7-R11
KINO-EHL-J6412C-R10	KINO-EHL-J6412C-R11
KINO-EHL-J6413C-R10	KINO-EHL-J6413C-R11
WAFER-EHL-J6412C-R10	WAFER-EHL-J6412C-R11
HYPER-EHL-J6412B-R10	HYPER-EHL-J6412B-R11
KINO-ADL-P-C-R10	KINO-ADL-P-C-R11
KINO-ADL-P-i3-R10	KINO-ADL-P-i3-R11
KINO-ADL-P-i5-R10	KINO-ADL-P-i5-R11
KINO-ADL-P-i7-R10	KINO-ADL-P-i7-R11

WAFER-ADL-P-CC-R10	WAFER-ADL-P-CC-R11
WAFER-ADL-P-i3C-R10	WAFER-ADL-P-i3C-R11
WAFER-ADL-P-i5C-R10	WAFER-ADL-P-i5C-R11
WAFER-ADL-P-i7C-R10	WAFER-ADL-P-i7C-R11
WAFER-ADL-N97C-R10	WAFER-ADL-N97C-R11
WAFER-ADL-N200C-R10	WAFER-ADL-N200C-R11

Affected by This Change

☒ Specifications ☐ Dimensions ☒ Appearance ☐ Package
☐ Certification ☐ Label ☒ BIOS ☒ Driver

For more details please refer to the latest datasheet or visit <http://www.ieiworld.com>.

Best Regards,
Maoxin Li
Product Manager
IEI Integration Corp.