



Micro-Star International Co., Ltd.

NO. 69, Lide St., Zhonghe Dist.,
New Taipei City, TAIWAN, R.O.C.

TEL: 886-2-3234-5599 (REP)

FAX: 886-2-2225-0272

Product Change Notice

☐ Approval / ☒ Inform Sheet

DATE: 2025 /12/08

Model No.	MS-CF05	PCN NO.	IPC-2025120801
ERP No.	R680E : 911-CF05-001/ 911-CF05-101 Q670E : 911-CF05-002/ 911-CF05-102		
Priority:	<input type="checkbox"/> URGENT <input checked="" type="checkbox"/> NORMAL		

Change Type		Old	New
<input type="checkbox"/> PCB Change			
<input type="checkbox"/> H/W Component Change			
<input checked="" type="checkbox"/> BIOS change	For R680E	ECF05IMS.850	ECF05IMS.860
	For Q670E	ECF05IMS.950	ECF05IMS.960
<input type="checkbox"/> Driver change			
<input type="checkbox"/> Others:			

Problem Description:

MS-CF05 channel BIOS Version Update.

Explanation:

1. Support Intel Bartlett Lake CPU.
2. Serial port 1~6 device setting show info "Reset Required" when serial port item set "disable" to "enable".
3. Add "Setup Search" function.

If you would like to update your customized BIOS to align with the standard BIOS version, please contact sales representative to submit an application.

☒ ECN Inform Sheet:

Customer's Reply:

- ☐ Accept
- ☐ Do not accept

Production Instruction:

- ☒ Cut in Immediately ☐ Running Change ☐ RMA Cut in

Explanation, Comments and Suggestions:

Issued By	Frances	Reviewed By	
------------------	---------	--------------------	--

Counter signature

☒ N/A

☐ Please sign this form and fax back not later than _____. If no confirmation or rejection has been received from you after the said date, we will assume your acceptance and implement the modifications.