



Micro-Star International Co., Ltd.

NO. 69, Lide St., Zhonghe Dist.,
New Taipei City, TAIWAN, R.O.C.

TEL: 886-2-3234-5599 (REP)

FAX: 886-2-2225-0272

Product Change Notice

☐ Approval / ☒ Inform Sheet

DATE: 2026/06/18

Model No.	MS-CF05	PCN NO.	IPC-20260618001
ERP No.	601-CF05-010/020 911-CF05-001/002/101/102		
Priority:	☐ URGENT ☒ NORMAL		

Change Type	Old	New
☐ PCB Change		
☒ H/W Component Change	N32-1030461-H06 S/PDIF Header	Remove
	N/A	C71-56106K1-AO5
☒ BIOS change	ECF05IMS.860 ECF05IMS.960	TBD
☐ Driver change		
☒ Others (6X/9X ERP):	601-CF05-010 / 911-CF05-001/101	606-CF05-100 / 916-CF05-007/103
	601-CF05-020 / 911-CF05-101/102	606-CF05-110 / 916-CF05-008/104

Problem Description:

New BIOS release and ERP update for MS-CF05 1.1

Explanation:

1. Update BIOS to support BTL-S P-Core CPU as below.

Code Name/ Processor Family	Processor Number
Bartlett Lake-S	213PE
Bartlett Lake-S	253PTE
Bartlett Lake-S	223PQE
Bartlett Lake-S	213PEF
Bartlett Lake-S	253PQE
Bartlett Lake-S	253PE
Bartlett Lake-S	273PQE
Bartlett Lake-S	223PE
Bartlett Lake-S	273PTE
Bartlett Lake-S	213PTE
Bartlett Lake-S	273PE
Bartlett Lake-S	223PTE

2. Enhance ECC-memory support by adding capacitor and remove S/PDIF connector.

If you require a customer-specific BIOS update, please contact your Sales to submit an application.

☒ ECN Inform Sheet:

Customer's Reply:

- ☐ Accept
- ☐ Do not accept

Production Instruction:

- ☒ Cut in Immediately
- ☐ Running Change
- ☐ RMA Cut in

Explanation, Comments and Suggestions:

Issued By		Reviewed By	
------------------	--	--------------------	--

Counter signature

☒ N/A

- ☐ Please sign this form and fax back not later than _____ If no confirmation or rejection has been received from you after the said date, we will assume your acceptance and implement the modifications.