



Micro-Star International Co., Ltd.

NO. 69, Lide St., Zhonghe Dist.,
New Taipei City, TAIWAN, R.O.C.

TEL: 886-2-3234-5599 (REP)

FAX: 886-2-2225-0272

Product Change Notice

☐ Approval / ☒ Inform Sheet

DATE: 2026/07/08

Model No.	MS-CF03/ 98F6/ CF09/ 98H3/ CF20/ 98E2/ 98M3/ 98L2/ 9892/ CF06/ CF02/ 98E6/ C926/ C910/ 98E3/ 98I6/ 98L9/ C924/ 98L3/ 98K9/ 98E1/ 98L1/ 98H9/ 98F7/ 98F1	PCN NO.	IPC2026708001
ERP No.	All impact ERP BOM		
Priority:	☐ URGENT ☒ NORMAL		

Change Type	Old	New
☐ PCB Change		
☒ H/W Component Change	M31-25Q1653-W03 WINBOND(W25Q16JVSSIQ)	M31-25V1612-M24 MXIC(MX25V1606FM2I03) / M31-25Q1612-W03 WINBOND(W25Q16RVCSJQ)
	M31-25Q1643-W03 WINBOND(W25Q16JVSNIQ)	M31-25V1602-M24 MXIC(MX25V1606FM1I03) / M31-25Q1602-W03 WINBOND(W25Q16RVCNJQ)
☐ BIOS change		
☐ Driver change		
☐ Others:		

Problem Description:

Winbond SPI flash EOL notice.

Explanation:

Please be advised that Winbond has announced the discontinuation (EOL) of its SPI Flash memory devices. Please refer to the attached supplier EOL notice for detailed information.

Supplier Final Last Time Buy (LTB)	Apr. 30, 2026	Sep. 30, 2026_for MSI
------------------------------------	---------------	-----------------------

In response to this change, alternative Winbond and MXIC SPI Flash memory devices will be implemented directly into the BOM as approved AVL components upon successful qualification.

Appendix:

Supplier EOL Notice	
 Winbond W25Q16JV_EOL.p	 Winbond W25Q20_EOL.pdf

☒ ECN Inform Sheet:

Customer's Reply:

- ☐ Accept
☐ Do not accept

Production Instruction:

- ☐ Cut in Immediately ☐ Running Change ☐ RMA Cut in

Explanation, Comments and Suggestions:**Issued By**

Sharon Pan

Reviewed By**Counter signature**

■ N/A

☐ Please sign this form and fax back not later than _____. If no confirmation or rejection has been received from you after the said date, we will assume your acceptance and implement the modifications.