

End-of-Life Announcement

- EOL of DDR4 DRAM Modules built with Samsung DDR4 4Gb F-die DRAMs -

Released date: Nov. 11, 2024

No: 24111101

Dear Valued Customers,

Apacer hereby announces the EOL of DDR4 DRAM Modules built with Samsung DDR4 4Gb F-die DRAMs, in response to Samsung will discontinue DDR4 4Gb F-die DRAMs. The alternatives are Samsung DDR4 4Gb G-die DRAMs. Please refer to below information for details.

- Non-Cancelable & Non-Returnable Last Buy Order: **Jun. 30, 2025**
- Last Time Shipment: **Dec. 31, 2025**
- Sample Available Date: **Now**

Affected Part Numbers as below:

- 1) Apacer's following part numbers will be EOL due to fixed BOM for Samsung DDR4 4Gb F-die. New part numbers will be applied as alternatives if necessary.

D13.23141S.001	D23.21180S.002	D43.22180S.006	D43.27180S.005
D13.23141S.003	D23.21211S.001	D43.22211S.002	D43.27180S.007
D21.23140S.002	D23.22180S.001	D43.23180S.003	D43.27180S.009
D23.21140S.001	D23.22180S.003	D43.23180S.004	D43.22180S.007
D23.22140S.001	D23.22185S.001	D43.23180S.007	D43.22180S.00A
D23.23140S.001	76.B163G.D250B	D43.23180S.008	D43.27180S.003
D23.23140S.002	D11.21217S.002	D43.23180S.009	D43.27180S.004
D23.23140S.003	D11.22185S.002	D49.23180S.001	D51.22213S.002
D23.23140S.004	D11.22186S.002	D51.22211S.001	D51.22216S.001
D23.23140S.006	D11.22186S.003	D51.23184S.002	D51.27184S.001
D43.23143S.001	D11.22186S.004	D51.23184S.003	DD3.23210S.001

75.A84H1.G000B	D11.22211S.001	D51.23215S.001	D11.21217S.003
75.A84H3.G000B	D11.23186S.001	D53.23184S.002	D11.22186S.005
75.B84H1.G010B	D23.23180S.002	D53.23184S.003	D11.22217S.001
76.A102G.D410B	D23.23180S.003	D53.23215S.002	D11.27186S.001
76.A302G.D330B	D23.23180S.004	D23.21180S.003	D11.2718FS.001
76.A355G.D330B	D23.23180S.005	D23.23180S.006	D11.2718FS.003
76.B196G.D760B	D23.23180S.00A	D11.2718FS.002	D13.22211S.002
76.B196G.D800B	D23.23180S.00B	D13.2718FS.001	D13.27186S.001
76.B302G.D440B	D29.23180S.001	D21.23180S.004	D19.27186S.001
76.B396G.D730B	D31.22182S.002	D21.23180S.005	D21.27187S.001
76.B396G.D740B	D31.22183S.001	D21.27187S.002	D23.22180S.004
D13.23142S.001	D31.22183S.002	D21.27215S.001	D23.22211S.002
D43.23147S.001	D31.22214S.002	D23.21180S.004	D23.23211S.001
D23.27140S.001	D31.23183S.001	D23.22211S.003	D23.27187S.001
D23.27140S.002	D31.23214S.001	D23.22211S.004	D23.27187S.002
D23.27140S.003	D33.22182S.003	D23.23180S.009	D31.23214S.002
D29.27140S.001	D33.22182S.004	D23.27187S.003	D31.27183S.002
D11.2318FS.002	D33.23183S.001	D23.27187S.004	D31.27185S.002
D13.22185S.002	D33.23185S.002	D29.23180S.002	D33.22182S.006
D13.22185S.003	D33.23185S.003	D31.27185S.001	D33.22214S.003
D13.2318FS.002	D41.23180S.003	D41.27180S.001	D33.27185S.001
D13.2318FS.003	D41.25180S.001	D43.22180S.009	D41.27180S.002
D21.22180S.001	D43.21180S.001	D43.27180S.002	D43.27180S.001
D21.22211S.001	D43.22180S.002	D43.27180S.00A	
D23.21180S.001	D43.22180S.003		

- 2) Apacer's following part numbers remain available for use because no fixed BOM is included in the part numbers. Replacement DRAM will keep being added to the BOM.

D22.23171S.001	D12.23186S.001	78.B1GS6.4060B	78.C1GS9.4060B
D23.23140S.005	D12.2318FS.001	78.B1GS6.40F0B	78.C1GSB.4010B
75.B84H3.G002B	D12.23211S.001	78.B1GS9.4040B	78.C1GSB.4040B
76.A125G.D550B	D13.22185S.001	78.B1GSB.4030B	78.C2GF5.4010B
76.A125G.D560B	D22.22180S.001	78.B1GSB.4050B	78.C2GG5.4010B
76.A151G.D510B	76.B125G.D390B	78.B1GSF.4030B	78.C2GG9.4010B

76.A325G.D590B	76.B125G.D430B	78.B1GTN.4020B	D33.23185S.001
76.A325G.D600B	76.B125G.D830B	78.B2GF4.4050B	D43.23180S.001
78.A1GN3.4010B	76.B225G.D240B	78.B2GFZ.4010B	D52.23184S.001
78.A1GN3.4020B	76.B325G.D360B	78.B2GG5.4000B	D72.23211S.001
78.A1GNL.4010B	76.B325G.D450B	78.B2GG9.4000B	76.B225G.D270B
78.A1GS3.4010B	76.B325G.D760B	78.C1GM0.4010B	78.C2GF1.4010B
78.A1GS3.4020B	78.A2GFZ.4000B	78.C1GM3.4010B	D22.23180S.001
78.A2GF7.4000B	78.B1GM0.4000B	78.C1GM3.4070B	D23.27187S.006
78.A2GFE.4000B	78.B1GM3.4000B	78.C1GM4.4010B	D52.23184S.002
78.A2GG4.4000B	78.B1GM3.4050B	78.C1GMS.4010B	D42.27215S.001
78.B1GN3.4040B	78.B1GM3.4060B	78.C1GMV.4010B	D42.27215S.002
78.B1GS3.4040B	78.B1GM4.4020B	78.C1GMV.4040B	D52.26184S.001
78.B2GF7.4010B	78.B1GMS.4050B	78.C1GN0.4010B	D52.27182S.001
78.B2GFE.4010B	78.B1GMS.4060B	78.C1GN0.4030B	D52.27184S.001
D42.23143S.001	78.B1GMV.4020B	78.C1GQV.4010B	D12.27186S.001
D12.27141S.001	78.B1GMV.4030B	78.C1GQV.4070B	D12.2718FS.001
D22.27140S.001	78.B1GN0.4000B	78.C1GS6.4010B	D22.27187S.001
D12.22185S.001	78.B1GN0.4020B	78.C1GS6.4070B	D22.27187S.002
D12.22211S.001	78.B1GQV.4060B	78.C1GS9.4050B	D23.27187S.005
D12.22217S.001	78.B1GRQ.4000B	D32.27185S.001	D32.26185S.001
D42.27180S.001	D33.2718AS.001		

Please contact our sales representative if you have any question about this EOL Announcement. Thank you for your understanding and cooperation.

Sincerely yours,
Apacer Technology Inc.