

PRODUCT END OF LIFE (EOL) NOTICE

1. EOL PRODUCTS

Product Name	Description
EC5xx-SD series	BOX PC

2. EOL REASONS

INTEL has formally announced EOL for Skylake PCH.

Supplier	Marketing Name
Intel	IC CHIP,SKYLAKE Mobile PCH-H, GLH110 SR2CA/BGA-837(INTEL)RoHS
Intel	IC CHIP,SKYLAKE Mobile PCH-H, GLQ170 SR2C5/BGA-837(INTEL)RoHS

3. EOL MILESTONES

Milestone	Definition	Date
Last Order Date	This is the date for customers to place their last order. The product will no longer be available after this date.	2025-08-15
Last Shipment Date	This is the last delivery date of the product. 1. This date is negotiable with DFI's headquarter or its branch offices. 2. The delivery date will highly depend on its actual lead time.	2026-08-15
End of Service Date	This is the date DFI will: - Discontinue updating software - Discontinue adding features - Discontinue new OS support - Discontinue bug fixes RMA services will be available depending on DFI's RMA policy.	2028-08-15

4. Recommended Product Replacements:

Product Name	Description
EC5xx-ADS	Intel Alder lake Fanless BOX PC
EC6xx-RPS	Intel Raptor lake BOX PC

DFI Inc.

Affected Items STD:

Part Number	Description
750-EC5000-100G	EC500-SD4061:Fanless, SD263, Q170, 4 COM, 6 USB, 1 VGA, 1 DVI-D, 1 HDMI, 2 LAN, 1 Line-out, 1 Mic-in, 1 CFast, DC9~36V, F/G SYSTEM RoHS
750-EC5101-000G	EC510-SD3G46E:Fanless, SD263,Q170, 3 COM, 16 DIO, 4 USB,1 HDMI, 1 DVI-D, 1 VGA,2 LAN, 1 Line-out, 1 Mic-in, 4 POE (802.3af), 1 PCI, DC 9~36V input, F/G SYSTEM RoHS
750-EC5101-100G	EC510-SD3G46:Fanless, SD263,Q170, 3 COM, 16 DIO, 4 USB,1 HDMI, 1 DVI-D, 1 VGA,6 LAN, 1 Line-out, 1 Mic-in, 1 PCI, DC 9~36V input, F/G SYSTEM RoHS
750-EC5111-000G	EC511-SD3G46E:Fanless, SD263,Q170, 3 COM, 16 DIO, 4 USB,1 HDMI, 1 DVI-D, 1 VGA,2 LAN, 1 Line-out, 1 Mic-in, 4 POE (802.3af), 1 PCIe x16, DC 9~36V input, F/G SYSTEM RoHS
750-EC5111-100G	EC511-SD3G46:Fanless, SD263,Q170, 3 COM, 16 DIO, 4 USB,1 HDMI, 1 DVI-D, 1 VGA,6 LAN, 1 Line-out, 1 Mic-in, 1 PCIe x16, DC 9~36V input, F/G SYSTEM RoHS
750-EC5311-000G	EC531-SD6881-H:Fanless, SD263-H110, 6 COM, 8 DIO, 8 USB3.0, 1 DVI-D, 1 VGA,2 LAN, 1 Line-out, 1 Mic-in, 1 PCIe x16 slot, 2 PCI slot, DC 9~36V input, F/G SYSTEM RoHS
750-EC5311-100G	EC531-SD6881-Q:Fanless, SD263-Q170, 6 COM, 8 DIO, 8 USB3.0, 1 HDMI, 1 DVI-D, 1 VGA,2 LAN, 1 Line-out, 1 Mic-in, 1 PCIe x16 slot, 2 PCI slot, DC 9~36V input, F/G SYSTEM RoHS
750-EC5321-000G	EC532-SD6881-H:Fanless, SD263-H110, 6 COM, 8 DIO, 8 USB3.0, 1 DVI-D, 1 VGA,2 LAN, 1 Line-out, 1 Mic-in, 2 PCIe x16 slot, 1 PCI slot, DC 9~36V input, F/G SYSTEM RoHS
750-EC5321-100G	EC532-SD6881-Q:Fanless, SD263-Q170, 6 COM, 8 DIO, 8 USB3.0, 1 HDMI, 1 DVI-D, 1 VGA,2 LAN, 1 Line-out, 1 Mic-in, 2 PCIe x16 slot, 1 PCI slot, DC 9~36V input, F/G SYSTEM RoHS

DFI Inc.

10F., No. 97, Sec. 1, Xintai 5th Rd., Xizhi Dist., New Taipei City 221, Taiwan (R.O.C.)
Tel: +886-2-2694-2986 FAX: +886-2-2694-5815

Affected Items DEV/ODM:

750-EC5000-101G
750-EC5000-103G
750-EC5000-104G
750-EC5000-105G
750-EC5000-131G
750-EC5000-151G
750-EC5101-101G
750-EC5111-001G
750-EC5111-002G
750-EC5111-101G
750-EC5111-103G
750-EC5111-131G
750-EC5111-150G
750-EC5311-001G
750-EC5311-031G
750-EC5311-101G
750-EC5321-001G
750-EC5321-002G
750-EC5321-003G
750-EC5321-004G
750-EC5321-101G
750-EC5321-102G
750-EC5321-151G
750-EC5321-152G
750-EC5321-153G
750-EC5322-000G
750-EC5330-000G
750-EC5330-100G
750-JPB220-091G
750-JPB220-092G
750-MEC511-001G
750-MRE20U-000G
750-MRE20U-001G
750-MRE510-001G

DFI Inc.

10F., No. 97, Sec. 1, Xintai 5th Rd., Xizhi Dist., New Taipei City 221, Taiwan (R.O.C.)
Tel: +886-2-2694-2986 FAX: +886-2-2694-5815

750-MRE510-002G
750-MRE511-001G
750-MRE511-002G
750-MRE511-003G
750-MRE511-004G
750-MRE511-005G
750-SZP500-000G
750-SZP500-001G
770-SD2631-001G
770-SD2631-002G
770-SD2631-101G
770-SD2631-102G
770-SD2631-103G
770-SD2631-104G
770-SD2631-105G
770-SD2631-136G
770-MR2631-081G
770-MR2631-082G

DFI Inc.

10F., No. 97, Sec. 1, Xintai 5th Rd., Xizhi Dist., New Taipei City 221, Taiwan (R.O.C.)
Tel: +886-2-2694-2986 FAX: +886-2-2694-5815