

Product Change Notice

Update Firmware Version for UT130-UFD9 BiCS5 Products

Release date: May. 9, 2025

Dear Valued Customers,

Thank you for your business and continued support for Apacer products. This PCN is being issued to inform you of a firmware update for UT130-UFD9 BiCS5 standard temperature products. Details of the change are provided in the table below. Apacer will provide all necessary support to ensure a seamless transition. If you have any questions or concerns regarding the content of this notification, please get in touch with Apacer sales representatives.

PCN Number	E250509-1	Release Date	May. 9, 2025
Action Levels	<div><input type="checkbox"/> Critical: Immediate change required</div> <div><input type="checkbox"/> Warning: Change as soon as possible</div> <div><input checked="" type="checkbox"/> Recommended: Optional, but suggested</div> <div><input type="checkbox"/> Informational: No immediate action required</div>		
Affected Product Model	UT130-UFD9 BiCS5		
Subject of Change			
To support wide temperature products and to align firmware version with all UT130-UFD9 BiCS5 product lines, firmware version is updated from UHFM20.4 to UHFUA0.1 for UT130-UFD9.			
Description of Change			
Apacer has updated the firmware version from UHFM20.4 to UHFUA0.1, respectively, with the following changes: <div><div>1. Optimize compatibility for handshaking.</div><div>2. Support for wide temperature products.</div></div>			
Recommended Action			
Apacer will continue to supply UT130-UFD9 BiCS5 with the old firmware, but we recommend qualifying with the latest version for improved compatibility and support.			

Affected Part Numbers

Capacity	Existing Part Numbers	New Part Numbers
	Standard Temperature	Standard Temperature
128GB	AN6.Z82HGV.00101	AN6.Z82HGV.00102
256GB	AN6.Z82JGV.00101	AN6.Z82JGV.00102
512GB	AN6.Z82KGV.00101	AN6.Z82KGV.00102
1TB	AN6.Z83AGV.00101	AN6.Z83AGV.00102

Schedule

Sample available date: Ready

Product Center
Apacer Technology Inc.